

# Appendix C – Examples of Best Practice

## Framework Contract for Wetland Restoration Works



## Bed Level Raising And Narrowing With Hoggin and Rejects: BUCKHERD BOTTOM

Eroded channel through  
pasture woodland, before  
restoration.



March 2013

Restored meander through  
pasture woodland, after  
restoration.



September 2014

Eroding artificial drain in mire,  
before restoration.



December 2014

Eroding artificial drain through  
wet heath, after infill.




March 2013



Meanders, before restoration July 2012



Meanders, after restoration October 2014



Artificial drain, before infill July 2012



Artificial drain, after infill August 2012

## Before Restoration

Eroding end point of previous mire restoration taken from concrete bridge



Picket Bottom, May 2014

## 3 months after restoration

Concrete bridge on open forest replaced with a gravel ford, bed level raised and channel narrowed



Picket Bottom, October 2014